



0 500 1000 Feet

Explanation

- Proposed monitoring well
- EPA monitoring well
- Schlumberger monitoring well
- Lear monitoring well
- TCEQ monitoring well

- Total Cr above 10 µg/L
- Total Cr above 50 µg/L
- Total Cr above 100 µg/L

EA ENGINEERING,
SCIENCE, AND
TECHNOLOGY

WEST COUNTY ROAD 112
GROUND WATER PLUME SITE
MIDLAND COUNTY, TEXAS

**Proposed Additional
Monitoring Wells
Location Map**

DESIGNED BY DWR	DRAWN BY CRS	CHECKED BY DWR	SCALE 1:12,000	DATE 08/30/2011	PROJECT NO EPA6.0000.05	FIGURE
--------------------	-----------------	-------------------	-------------------	--------------------	----------------------------	--------